

4. COMPLETE SET

4.1. The Complete Set contains the following articles and service forms and records listed in Table 2.

Table 2

Designation	Name	Q-ty	Notes
1. 412152.001	Combined ionizing radiation measuring instrument PKCE-104	1	In manufacturer's package P.3 and 4 are used as dishes for measurement of radio-nuclide caesium-137 specific radio-activity
2	"Korund" battery TY 16-729.060-81	1	
3. 735211.001	Cover	1	
4. 735211.001	Cover	1	
5. 412152.001C	Certificate	1	

Note: The instrument modification numbers of P.1 and details P.3 and 4 are designated by the instrument color and structural styling and are indicated by the manufacturer when released

5. SAFETY PRECAUTIONS

5.1. After measuring samples it is necessary to deactivate thoroughly dishes by washing them with synthetic detergents.

5.2. While operating with the removed cover be careful and do not damage film filters of gas discharge counters because in switched on state the counters are energized with high voltage (of the order of 400V).

5.3. Sample substances with detected radioactivity and decontamination radioactive waste are subject to burying in places appointed by the sanitary inspection.